

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲੋਂ

ਪ੍ਰਿੰਸੀਪਲ,
ਅਕਾਲ ਅਕੈਡਮੀ, ਚੀਮਾ
ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰਬਰ: 172


ਮਿਤੀ: 16/6/25

ਵਿਸ਼ਾ:- ਸਾਲ 2025-26 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਸਬੰਧਿਤ ਜੇ.ਈ. ਵੱਲੋਂ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਆਪ ਵੱਲੋਂ ਆਨਲਾਇਨ ਖਜਾਨੇ (Head of Account 8782-00-102-01-00) ਵਿੱਚ ਬਾਬਤ ਰੁਪਏ 20000/- (ਵੀਹ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) Receipt. No. 17904345 ਮਿਤੀ: 12/06/2025 ਰਾਹੀਂ ਜਮਾਂ ਕਰਵਾ ਦਿੱਤੀ ਗਈ ਹੈ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਵੱਲੋਂ ਨਾਲ ਨੱਥੀ ਕੀਤਾ ਗਿਆ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਜਿਸ ਦੀ ਜਾਰੀ ਕਰਨ ਦੀ ਮਿਤੀ: 03/03/2025 ਹੈ, ਇਸ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਉਕਤ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ 31/03/2026 ਤੱਕ ਵਧਾਉਣ ਦੀ ਜਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਨਿੱਜੀ ਹੋਵੇਗੀ ਅਤੇ ਮਿਆਦ ਵਧਾਉਣ ਉਪਰੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 03/03/2026 ਤੋਂ ਬਾਅਦ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।


ਨੱਥੀ:- ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 1967 ਮਿਤੀ: 27.05.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Part-II


Building Safety Report

Name of School: AKAL ACADEMY, CHEEMA (C.B.S.E)

Sh. ADITYA KANSAL (Junior Engineer) has visited the above mentioned school on dated 04/06/2025 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity with valid Fire Safety Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31.03.2026**


(Aditya Kansal)
J.E


Sub Divisional Engineer
Const. Sub Divn.No.2 PWD, B&R
Sangrur.